## Message Text

UNCLASSIFIED

PAGE 01 CANBER 06347 210808Z

12

**ACTION FBO-01** 

INFO OCT-01 EA-07 ISO-00 /009 W

----- 048379

P 210630Z NOV 73

FM AMEMBASSY CANBERRA

TO SECSTATE WASHDC PRIORITY 2046

**UNCLAS CANBERRA 6347** 

FOR: A/FBO

E.O. 11652: N/A TAGS: ABLD AS

SUBJ: BUILDINGS: EMERGENCY REPAIRS TO PROPERTY 05307

61 FRANKLIN ST. FORREST

- 1. TWO VERY UNFORTUNATE OCCURRENCES HAVE TAKEN PLACE ALMOST SIMULTANEOUSLY IN THE ABOVE RESIDENCE DURING THE ABSENCE FROM CANBERRA, OF THE OCCUPANT.
- (1) THE VALVE FLOAT MECHANISM IN THE ATTIC WATER STORAGE TANK FAILED TO FUNCTION PROPERLY, ALLOWING AN UNINTERRUPTED OVERFLOW OF WATER ONTO MASTER BEDROOM CEILING, DAMAGING SAME TO POINT REQUIRING ALMOST COMPLETE REPLACEMENT.
- (2) A PIPE FROM THE HOT WATER HEATING PLANT DEVELOPED A BETWEEN FLOOR LEAK, ALLOWING EXCESSIVE SEEPAGE INTO DINING ROOM AREA AND DOWNSTAIRS POWDER ROOM. REPEATED ATTEMPTS HAVE BEEN MADE TO REMOVE RUST WATER STAINS FROM DINING ROOM DRAPES, AS WELL AS CARPETING IN BOTH DINING AND POWDER ROOMS TO NO AVAIL. THROUGH INVESTIGATION OF BOTH INCIDENTS REFLECTS NO BLAME ATTRIBUTABLE TO HOUSE OCCUPANT, WITH SITUATION REGRETFULLY AGGRAVATED BY TENANT'S ABSENCE AWAY FROM CANBERRA.
- 2. ABOVE DAMAGED AREAS OF HOUSE ARE CURRENTLY UNUSABLE IN THEIR PRESENT STATE, AND EVERGENCY REPAIR/RENOVATION FUNDS ARE URGENTLY REQUESTED TO RECTIFY DAMAGE AS SOON AS POSSIBLE.
  UNCLASSIFIED

UNCLASSIFIED

PAGE 02 CANBER 06347 210808Z

3. TO CORRECT DAMAGE INFLICTED UNDER (1) ABOVE:

A. INSTALLATION OF COPPER OVERFLOW DRAIN PIPE INCORPORATED INTO ATTIC SOTRAGE TANK, AND REPLACEMENT OF ENTIRE FLOAT MECHANISM: A\$190.00 US\$283.00

B. REPLACEMENT OF PLASTER CEILING IN MASTER BEDROOM, BEYOND REPAIR, LOCATED BELOW STORAGE TANK A\$150.00 US\$223.46.

4. TO CORRECT DAMAGE INFLICTED UNDER (2) ABOVE:

A. REPLACE/REPAIR SECTIONS OF HOT WATER PIPING LOCATED ABOVE DINING ROOM; INCLUDING RENOVATION OF PLASTER CEILING AND WALLS (DAMAGED BUT REPAIRABLE) IN DINIGN ROOM (INCLUDING REPAINTING AS REQUIRED) A\$170.00 US\$253.25.

B. REPLACE PERMANENTLY STAINED CARPETING IN DINING ROOM AND DOWNSTAIRS POWDER ROOM: A\$325.00 US\$484.15

C. REPLACE PERMANENTLY STAINED FULL WALL LINED DRAPERIES IN DINING ROOM: A\$120.00 US\$178.76

5. REQUEST URGENT CABLE ALLOTMENT INCREASE, IN THE AMOUNT OF US\$1422.62 TO EFFECT EARLY REPLACEMENT/REPAIRS OF ITEMS CITED ABOVE.
GREEN

UNCLASSIFIED

NNN

## Message Attributes

Automatic Decaptioning: X Capture Date: 01 JAN 1994 Channel Indicators: n/a

**Current Classification: UNCLASSIFIED** 

Concepts: n/a Control Number: n/a Copy: SINGLE Draft Date: 21 NOV 1973 Decaption Date: 01 JAN 1960 Decaption Note: Disposition Action: n/a Disposition Approved on Date: Disposition Authority: n/a Disposition Case Number: n/a

Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:

Document Number: 1973CANBER06347 Document Source: CORE Document Unique ID: 00

Drafter: n/a Enclosure: n/a Executive Order: N/A Errors: N/A Film Number: n/a From: CANBERRA Handling Restrictions: n/a

Image Path:

Legacy Key: link1973/newtext/t19731121/aaaaaovh.tel Line Count: 90

Locator: TEXT ON-LINE

Office: ACTION FBO Original Classification: UNCLASSIFIED Original Handling Restrictions: n/a

Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 2

Previous Channel Indicators: Previous Classification: n/a Previous Handling Restrictions: n/a Reference: n/a Review Action: RELEASED, APPROVED Review Authority: kelleyw0

Review Comment: n/a
Review Content Flags: Review Date: 30 JAN 2002

**Review Event:** 

Review Exemptions: n/a
Review History: RELEASED <30-Jan-2002 by bryansd0>; APPROVED <06-Feb-2002 by kelleyw0>

**Review Markings:** 

Declassified/Released US Department of State EO Systematic Review 30 JUN 2005

**Review Media Identifier:** Review Referrals: n/a Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

Secure: OPEN Status: NATIVE

Subject: BUILDINGS: EMERGENCY REPAIRS TO PROPERTY 05307 61 FRANKLIN ST. FORREST

TAGS: ABLD, AS To: STATE

Type: TE

Markings: Declassified/Released US Department of State EO Systematic Review 30 JUN 2005